

## Thank you for choosing The3DPC!

Velkase 7" LCD Side panel case Tools needed: M3 Allen wrench and Phillips screwdriver


- 1) Begin by removing the front and the motherboard side 2) Take the LCD panel Base and set the LCD panel inside panel from the case. (use the Velkase assembly manual)

with the IO matching the IO cutouts in the base.



- 3) Mount the LCD panel surround on top of the LCD panel 4) Next, attach the LCD panel to the motherboard side and turn whole case over. Insert the included four M3x12mm screws to the 4 outermost holes (not the threaded inserts) and tighten down. **DO NOT OVER** TIGHTEN!

panel. The IO panel should be facing the back of the case. Pick where you would like it mounted. Use the included four M3 x 5mm countersunk screws. **DO NOT OVER TIGHTEN!** 



5) Install the side panel and front panel per the Velkase assembly manual. Attach your video cable and USB power cable. You now have a full mobile PC.



